STEP 1: PUT MODULE INTO UPDATE MODE
   a) Disconnect power and USBC
   b) Plug them in again, and within 3 seconds press and hold buttons 7 and 8:

1	2
3	4
5	6
7	8

When you hear beep for 3 seconds, it is in update mode.

STEP 2: RUN IAP SOFTWARE
   a) Select COM port and baud rate, then select *Connect*
   b) Enter the details as below.
      Set address as below (VERY important)
      Set the .bin file path.
      Select *Install*

Alternating flashing red and blue lights indicates success. The device will put itself into normal mode.